



REPLACEMENT FOR
MINICA TONY

REPLACEMENT FOR
MINICA '88

REPLACEMENT FOR
NATIVA '00-'04

214-1510
CORNER LAMP
R MB 377062
L MB 377061
50PCS 1.68CFT



214-1516-N
CORNER LAMP
R MB 598198
L MB 598197
40PCS 4.38CFT



114-1121-LD-E1
HEAD LAMP
R
L
PCS
CFT



H4/W21W/W5W

TBA

214-1616
FRONT LAMP
R MB 330492
L MB 330491
50PCS 3.62CFT
00-214-1616 LENS
200PCS 0.77CFT



214-1516-0
CORNER LAMP
R MB 598196
L MB 598195
40PCS 2.21CFT



114-1121-LD-E6
HEAD LAMP
R 8301A-312HA
L 8301A-311HA
PCS
CFT



H4/W21W/W5W

TBA

214-1401
SIDE LAMP
MB 330501
200PCS 3CFT



214-1945
TAIL LAMP
R MR 124742
L MR 124741
10PCS 3.35CFT



314-2010-AS
FOG LAMP
R
L MR496369
PCS CFT



H3

TBA

214-1931
TAIL LAMP
R MB 33052
L MB 33051
PCS CFT



TBA

214-1928
TAIL LAMP
R MB 598202
L MB 598201
20PCS 6.51CFT



214-19A1
TAIL LAMP
R 8330A060
L 8330A059
PCS
CFT



P21/5W/P21W/PY21W

TBA



MITSUBISHI