



REPLACEMENT FOR

## PLATINA '02 MEXICO TYPE



REPLACEMENT FOR

## PRIMASTAR '01



### 215-1195-LD-E

HEAD LAMP  
R 26010-00QAA  
L 26060-00QAB  
4PCS 6.86CFT



H4/PY21W/W5W

### 442-1133-LD-EM

HEAD LAMP  
R 7700311372  
R 4408723  
L 4414032  
4PCS 5.9CFT



H4/W5W

### 551-2008-UE

FOG LAMP  
R 8200301027  
L 8200301026  
R 8200002470  
L 8200002469  
24PCS  
2.83CFT



H11

R 26150-AU325  
L 26155-AU325  
R 26150-89905  
L 26155-89905

### 551-1608-UE-Y

CORNER LAMP  
R 088132  
L 088131  
R 89005713  
L 89005711  
R 8200007030  
L 8200007031  
20PCS 6.2CFT



P21W

### 551-1608-UE-C

CORNER LAMP  
R 89010138  
L 89010139  
20PCS 6.2CFT



P21W

### 551-1932-UE

TAIL LAMP  
R 087680  
L 087681  
6PCS 3.77CFT



PY21W/W5W

### 551-2004-UE

FOG LAMP  
R 7701045717  
L 7701045718  
R 67736905  
L 67736895  
24PCS 3.90CFT



H1

### 442-1935

TAIL LAMP  
R 4414576  
L 4414575  
PCS CFT



P21W/P21/5W

TBA

1 TAIL GATE

### 442-1944

TAIL LAMP  
R 82003-36834  
L 26555-00QRS  
PCS CFT



P21W/P21/5W

TBA

2 TAIL GATE

### 442-1304

BACK LAMP  
R 26554-00QAE  
L  
PCS CFT



TBA

### 442-2902

REFLECTOR  
26079-00QAE  
PCS CFT



TBA