



REPLACEMENT FOR

OUTLANDER '05



REPLACEMENT FOR

PAJERO MONTERO '83-'91 4G54 LO47 V30




214-1179-LD-E/EM
HEAD LAMP
R 8301A174
L 8301A173
PCS CFT



HB3/H1/WY21W/W5W TBA

214-1203-1
LIGHT CASE
R MB 283932
L MB 283931
10PCS 2.47CFT



214-2802
F/SIDE BUMPER
R MB 369554
L MB 369553
20PCS 2.5CFT




214-1179-LDEM7
HEAD LAMP
R 8301A176
L 8301A175
PCS CFT



HB3/H1/WY21W/W5W TBA

214-1203-2
LIGHT CASE
R MB 283576
L MB 283575
10PCS 2.47CFT



214-2803
F/SIDE BUMPER
R MB 369582
L MB 369581
10PCS 1.5CFT



214-1992-UE2
TAIL LAMP
R 8330A050
L 8330A049
PCS CFT



W5W/WY21W/W16W/W21/5W TBA

214-1507
CORNER LAMP
R MB 283670
L MB 283669
20PCS 2.18CFT
00-214-1507 LENS
100PCS 3.36CFT




214-1992-UER
TAIL LAMP
R 8330A048
L 8330A047
PCS CFT



W5W/WY21W/W16W/W21/5W TBA

214-1922
TAIL LAMP
R MB 283722
L MB 283721
20PCS 4.45CFT
00-214-1922 LENS
100PCS 2.75CFT




214-2801
SIDE BUMPER
R MB 369552
L MB 369551
10PCS 1.4CFT





REPLACEMENT FOR

PAJERO MONTERO '92-'94 V32 V34 SJ45 4G54 '92

214-1120-RD-E **43T**
LD-E
 HEAD LAMP
 RD:
 R MB 831068
 L MB 831067


LD:
 R MB 831066
 L MB 831065
 6PCS 4.74CFT



H4

214-1215-1-2-3
 LIGHT CADE
 2:
 R MB 831056
 L MB 831055

3:
 R MB 831058
 L MB 831057
 5PCS 1.4CFT



214-2809-6 **BASE**
 F/SIDE BUMPER
 R MB 831048
 L MB 831047
 5PCS 3.87CFT



214-1531-AE-UE
 CORNER LAMP
 R MB 831082
 L MB 831081
 20PCS 2.8CFT



P21W/W5W

214-1530-A
 CORNER LAMP
 R MB 831080
 L MB 831079
 R MR 124956
 L MR 124955
 20PCS 4.53CFT




P21W/W5W

214-2810
 FRONT SIDE BUMPER
 R MB 831050
 L MB 831049
 10PCS 6.53CFT



214-1938-1A
 TAIL LAMP
 R MB 831490
 L MB 831489
 10PCS 4.7CFT



214-1938-2A
 TAIL LAMP
 R MB 831086
 L MB 831085
 10PCS 4.7CFT



214-2808-6 **RS.LS.SR**
 R/SIDE BUMPER
 R MB 831720
 L MB 831719
 5PCS 2.38CFT



214-1415-C
 SIDE LAMP
 200PCS 2.85CFT



214-1938-NA
 TAIL LAMP
 R
 L
 10PCS 4.7CFT



214-2808-2 **BASE**
 REAR SIDE BUMPER
 R MB 831054
 L MB 831053
 5PCS 2.38CFT



214-1415
 SIDE LAMP
 MB 831091
 200PCS 2.85CFT



214-1946-UE
 TAIL LAMP
 R MR 124964
 L MR 124963
 20PCS 2.12CFT



P21W/P21/5W

MITSUBISHI



REPLACEMENT FOR

PAJERO MONTERO '98 V33



REPLACEMENT FOR

PAJERO MONTERO '00

214-1146-LD-E
 HEAD LAMP
 R MR 387534
 L MR 387533
 6PCS
 4.82CFT



H4

214-1938-2AD BLACK
 TAIL LAMP
 R
 L
 10PCS 6.01CFT



214-1159-LD-E2/EM2
 HEAD LAMP
 R MR548036
 L MR548035
 4PCS 7.6CFT



R MR548034
 L MR548033

H4/W21W/W5W

214-1556-AE
 CORNER LAMP
 R MR 387544
 L MR 387543
 20PCS
 4.47CFT



PY21/W5W

214-1938-1ADCR CHROMED
 TAIL LAMP
 R
 L
 10PCS 6.01CFT



214-2026-AE
 FOG LAMP
 R MR508190
 L MR508189
 R MR537966
 L MR537965
 12PCS
 3.03CFT



H3

214-1425
 SIDE LAMP
 R MB 821172
 100PCS
 0.90CFT



214-1938-2ADCR BLACK
 TAIL LAMP
 R
 L
 10PCS 6.01CFT



214-1971-6
 TAIL LAMP
 R
 L MR508201
 PCS CFT



W21W/W21W/21/5W TBA

214-1405P-X1
 SIDE LAMP
 50PRS 0.92CFT



214-1938-1NA
 TAIL LAMP
 R
 L
 10PCS 6.01CFT



214-1971-9
 TAIL LAMP
 R MR508504
 L
 PCS CFT



W21W/W21W/21/5W TBA

214-1946-UE
 TAIL LAMP
 R MR 124964
 L MR 124963
 20PCS 2.12CFT



P21W/P21/5W

214-1938-1AD CHROMED
 TAIL LAMP
 R MR 376354
 L MR 376353
 10PCS 6.01CFT



214-1317-UE
 BACK LAMP
 R MN133776
 L MN133775
 PCS CFT



P21W/P21W TBA

214-1320
 BACK LAMP
 R MR570142
 L MR570141
 PCS CFT



TBA

Toutes les pièces énumérées dans ce catalogue ne sont pas originaux. Alle die in diesem Katalog abgebildeten Artikel, sind nicht original Teile. All items shown in this catalogue are not original parts. Todos los productos de este catalogo no son originales. Tutti i particolari raffigurati in questo catalogo non sono originali.



REPLACEMENT FOR

PAJERO MONTERO '03

214-1159-LD-E1/EM1

HEAD LAMP

R

L

4PCS

7.6CFT



H4/W21W/W5W

214-1159-LDH

HEAD LAMP

R MN133754

L MN133753

PCS CFT



D2R/W21W/W5W

TBA

214-1982PXUEVCY

TAIL LAMP

5PRS

7.68CFT



214-1979 R-LD-AE L-LD-AE


TAIL LAMP

R MN133766

L MN133765

6PCS

5.19CFT



214-2030-UQD

FOG LAMP

MN133758

12PCS 2.0CFT



HB4

214-1982PXUECC

TAIL LAMP

5PRS

7.68CFT



214-1979-AE

TAIL LAMP

R MN133764

L MN133763

6PCS

5.19CFT



WY21W/W21/5W/W21W

214-1982PXUEV 214-1982PCUEV

TAIL LAMP

5PRS

7.68CFT



214-1979 R-RD-AE L-RD-AE


TAIL LAMP

R

L

6PCS

5.19CFT



214-1982PXLDUE 214-1982PCLDUE

TAIL LAMP

5PRS 7.68CFT



LHD

214-1317-UE

BACK LAMP

R MN133776

L MN133775

PCS CFT



P21W/P21W

214-1982PXRDU 214-1982PCRDUE

TAIL LAMP

5PRS 7.68CFT



RHD

MITSUBISHI



REPLACEMENT FOR

PAJERO SPORT '04 CHINA TYPE



REPLACEMENT FOR

PAJERO '02 MINI

REPLACEMENT FOR

NEW PAJERO '07

214-1186-LD-E/EM
HEAD LAMP
EM:
R
L 8301A893
PCS
CFT



H9/H11/WY21W/W5W **TBA**

114-1121-LDEM1
HEAD LAMP
R
L MR566771
PCS
CFT



H4/W21W/W5W **TBA**

214-1162-RD
HEAD LAMP
R MR 414930
L MR 414929
PCS CFT



H4/PY21W/P21/5W **TBA**

214-1186-LDHEM
HEAD LAMP
R
L 8301A895
PCS
CFT



TBA

114-1121-LDEM6
HEAD LAMP
R
L
PCS
CFT



H4/W21W/W5W **TBA**

214-2027
FOG LAMP
R MR 439836
L MR 439835
PCS CFT



H3 **TBA**

214-19A5-UE
TAIL LAMP
R 8330A354
L
PCS CFT



WY21W/W21W/W21/5W **TBA**

TBA

214-1977
TAIL LAMP
R MR 535074
L MR 535073
PCS CFT



P21W/PY21W/P21/5W **TBA**

TBA

TBA

TBA

TBA

