



REPLACEMENT FOR

TEANA '04

REPLACEMENT FOR

TEANA '06 CHINA TYPE

115-1114-RD LD

HEAD LAMP

RD:

R 26550-9Y025
L 26555-9Y025
L 26065-9Y000
4PCS CFT



H7/H4/WY21W/W5W

LD:

R 26010-9W200
L 26060-9W200

115-1114-LDH

HEAD LAMP

R 260159-W210-B019
L 260659-W210-B019
R 26010-2YA10-22
L 26060-2YA10-22
4PCS CFT



HID/H4/WY21W/W5W

3.5cc

115-1118-LDH-M

HEAD LAMP

R

L 26060-7W51A-B019
PCS CFT



D2S/H7/W5W/WY21W

TBA

551-2008-UE

FOG LAMP

R 8200301027
L 8200301026
R 8200002470
L 8200002469
24PCS
2.83CFT



H11

R 26150-AU325
L 26155-AU325
R 26150-89905
L 26155-89905

115-2011

FOG LAMP

R 26150-YJ000-23
L 26155-YJ000-23
PCS CFT



H11

TAIWAN TYPE

TBA

115-1928

TAIL LAMP

R

L 265557W51A-A104
PCS
CFT



LED

TBA

215-1441N-U

SIDE LAMP

26160-9Y000
100PCS 0.90CFT



W5W

115-1920-U

TAIL LAMP

R

L 26060-9Y025
R 26550-9W200
L 26555-9W200
6PCS 10.2CFT



W16W/WY21W/W21/5W

115-1924-A

TAIL LAMP

R B6550-YJ000-23
L B6555-YJ000-23
L 26555-YJ010-23
PCS
CFT



LED

TBA

'05

NISSAN