



REPLACEMENT FOR  
**WIRA '93**

**WIRA '04**

**214-1126-RD**  
HEAD LAMP **LD-E**  
RD:  
R MR 124334  
L MR 124333  
6PCS 4.81CFT

43T



H4/W5W

**214-1126PXR**  
HEAD LAMP  
R  
L  
2PRS 3.08CFT



H4/W5W

**214-1126-RD-2**  
HEAD LAMP  
R PW547042  
L PW547041  
6PCS 4.81CFT



H4/W5W

**214-1534-U**  
CORNER LAMP  
R MB847336  
L MB847335  
20PCS  
5.18CFT



**214-2013**  
FOG LAMP  
R EP 586125  
L EP 586124  
PCS  
CFT



TBA

**214-1534-B-2CC**  
CORNER LAMP  
R PW547012  
L PW547011  
20PCS 2.18CFT



PY21W

**214-1534PXU**  
CORNER LAMP  
R  
L  
10PRS  
2.17CFT



**214-1942**  
TAIL LAMP  
R MR 106501  
L MR 106500  
10PCS  
4.34CFT



**214-1534-B-2CY**  
CORNER LAMP  
R PW547894  
L PW547893  
20PCS 2.18CFT



PY21W

**214-1404**  
SIDE LAMP  
R MB124340  
L MB124339  
50PCS  
2.66CFT



**214-1309**  
BACK LAMP  
R MB847566  
L MB847565  
20PCS  
4.59CFT



**214-1953**  
TAIL LAMP  
R PW 537462  
L PW 537461  
10PCS  
4.34CFT



**214-1405N-AE-Y**  
SIDE LAMP  
MB 847540  
CB21172  
50PCS  
0.92CFT



**214-1310L**  
BACK LAMP  
R PW537466  
L PW537465  
10PCS  
2.74CFT

'96



**214-1310R**  
BACK LAMP  
R  
L  
10PCS  
2.74CFT

'96

